


# **2015 Corvette: Service Bulletin: Instrument Cluster Driver Information Center Goes Blank or Analog Speedometer Inaccurate**



**Subject:** Instrument Cluster Driver Information Center Goes Blank or Analog Speedometer Inaccurate

**Model and Year:** 2015 Chevrolet Corvette Built Prior to March 5, 2015

**Source:** Chevrolet Dealer Service Technical Bulletin

**Bulletin Number:** PI1436

**Date:** March 10, 2015

2015 Chevrolet Corvette [1G1YT3D63F5601580] | Corvette Service Manual 7527625 | Document ID: 4104798

## #PI1436: Instrument Cluster Driver Information Center Goes Blank or Analog Speedometer Inaccurate - (Mar 10, 2015)

**Subject:** Instrument Cluster Driver Information Center Goes Blank or Analog Speedometer Inaccurate

**Models:** 2015 Chevrolet Corvette  
Built Prior to March 5, 2015



**Attention:** This PI also applies to any of the above models that may be Export vehicles.

### Condition / Concern

Some customers may comment that the driver information center in the instrument cluster may go blank, or the analog speedometer may read 200 mph (322 km/h) and may operate backwards.

This may be caused by a software anomaly.

### Recommendation / Instructions

An updated software calibration has been released to address these conditions.

Update the Instrument Cluster using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the Instrument Cluster Programming and Setup in SI.

**Important:** This procedure is a USB flash drive programming event. This **IS NOT** a standard TIS2WEB programming event. The radio must be on during this procedure. The USB File Transfer procedure is not required for vehicles with UDC.

**Important:** Verify the battery voltage is more than 12 volts but less than 16 volts before proceeding with reprogramming. The battery must be fully charged **BEFORE** reprogramming.

**Important:** During reprogramming, the battery voltage must be maintained within the proper range of 12-15.5 volts. **CONNECT** the approved Midtronics® PSC 550 Battery Maintainer (SPS Programming Support Tool (EL-49642) to the vehicle or the GR8 (EL50313) in the power supply mode.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2015-corvette-service-bulletin-instrument-cluster-driver-information-center-goes-blank-or-analog-speedometer-inaccurate-1229.html>