

2000 Corvette: Service Bulletin: Low Tire Pressure Message on DIC, Slow Air Loss

Source: Chevrolet Dealer Service Bulletin

Number: 00-03-10-001

Subject: Low Tire Pressure Message Repeatedly Displayed on DIC, Slow Air Loss
From Tire and Wheel Assembly (Replace Wheel Assembly)

Model Year: 2000 Chevrolet Corvette Built prior to VIN Breakpoint Y5001500


Condition

Some customers may comment on a repeated occurrence of having a low tire pressure message displayed on the Driver Information Center for a specific tire and wheel location.

Cause

Wheels that exhibit a repeat leak down condition may have been machined in such a manner that the valve stem/tire pressure sensor counterbore is too deep, resulting in air leakage past the sensor's seal.

Correction



With the tire and valve stem/tire pressure monitor removed from the suspect wheel, place a penny in the counterbore where the valve stem/tire pressure monitor seats on the inside of the wheel. If the penny sits in the counterbore so that it is below the unmachined surface of the wheel at the points indicated by the arrows in the illustration (counterbore depth more than 1.1 mm (.043 in)), replace the wheel assembly with the appropriate service part indicated in the chart below.

Parts Information

Part Number	Description
9593798	Wheel, Front
9593800	Wheel, Rear

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2000-corvette-service-bulletin-low-tire-pressure-message-on-dic-slow-air-loss-370.html>