

# 1956 Corvette: Service Bulletin: Instability Above 60 MPH

**Subject:** Instability Above 60 MPH

**Model and Year:** 1956 Corvettes (Serial Numbers Listed)

**Source:** Chevrolet Technical Service Bulletin

**Bulletin No:** DR #267

**Section:** III

**Date:** October 10, 1956

**TO: ALL CHEVROLET DEALERS**

When an unstable condition exist above 60 MPH on 1956 Corvettes between Serial No. E56S 3175 and E56S 4156, the parts listed below should be installed:

## PARTS DATA

<b>Part</b>	<b>Required</b>	<b>Part No.</b>
Steering Idler and 3rd Arm Assembly	1	3733215
Special Caster Shim (Round 1" Diameter) Install between idler arm bracket and crossmember to lower Idler Arm.	2	3733479

- Use bolts, part no. 181639.

Special Shim (Tapered) 2 3733477

- Install tapered shim with thick end to rear between frame side rails and front crossmember to increase caster.
- Use bolts, part no. 181639 at rear.

Bolt 1-1/4" long 6 181639

Wheel Alignment (Revised)

- Caster both sides  $1\frac{3}{4}^{\circ}$  to  $2\frac{3}{4}^{\circ}$
- Camber both sides  $0^{\circ}$  to  $1^{\circ}$
- Toe-in both sides  $1/8"$

All of the above applies to the 1957 Corvette.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1956-corvette-service-bulletin-instability-above-60-mph-962.html>