

# 1966 Corvette: Engineering Service Letter: Top Radiator Inlet Hose Interference

**Subject:** Top Radiator Inlet Hose Interference (No. 444-T.I.)

**Model and Year:** 1967 Corvette - 427 Mark with Power Steering

**Source:** Chevrolet Engineering Service Letter

**Bulletin No:** TNP #66-4

**Section:** VI - Engine - Continued

**Date:** 7-11-66

Some early 427 Corvettes equipped with power steering may experience radiator top hose interference with the generator pulley-fan and/or the hood reinforcement. This is due to the radiator support being mounted too close to the engine and the hood interference is due to the usage of early design radiator hoses.

Effective with vehicles built February 15, 1966, Serial No: 194376S113952, the latest parts and designs will be used.

Service correction for early models will be made available.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1966-corvette-engineering-service-letter-top-radiator-inlet-hose-interference-1004.html>