

2008 Corvette: GM TechLink: CD Player Condition

Some owners of a 2008 Corvette equipped with radio US9 - MP3, WMA and 6 disc in-dash CD player may comment that when starting their vehicle, the music disc playing on the current ignition cycle is not the music disc they were listening to during the previous ignition cycle.

This concern is typically intermittent and occurs only when the driver turns the vehicle off while listening to the first 30-45 seconds of the first song on the 2nd, 3rd, 4th, 5th or 6th disc.

Replacing the radio will NOT correct this concern. This is a normal operating characteristic and no repairs are recommended.

- Thanks to *Dino Poulos*

October 2008 - GM TechLink

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2008-corvette-gm-techlink-cd-player-condition-110.html>