

# 1965 Corvette: Engineering Service Letter: RPO L-76 327-365 H.P. Holley Carburetor Parts Changes

T.N. #7 - June 30, 1965

## SECTION VI m CARBURETOR AND FUEL PUMP - CONTINUED

### MISCELLANEOUS

#### **CORVETTE WITH 365 HP - 327 CU IN ENGINE AND HOLLEY CARBURETOR DYING ON QUICK RIGHT TURNS.**

Condition can be corrected by installing the following Holley parts:

Floats P/N 16R - 429A

Needles & Seats P/N 18R - 96A

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1965-corvette-engineering-service-letter-rpo-1-76-327-365-h-p-holley-carburetor-parts-changes-115.html>