

# 2005 - 2009 Corvette: Service Bulletin: Removable Top Squeaks When Stowed Away (Install Velcro)

**#06-08-67-002A: Removable Top Squeaks When Stowed Away (Install Velcro) - (Jun 4, 2008)**

**Subject:** Removable Top Squeaks When Stowed Away (Install Velcro®)

**Models:** 2005-2009 Chevrolet Corvette

## Condition

Some customers may comment that the removable top squeaks when stowed away in the trunk.

## Cause

This noise may be caused by the removable top rubbing on the removable top retainers.

## Correction

Apply a piece of Velcro® (cloth side) to the removable top retainer.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a

General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

[https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2009-](https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2009-corvette-service-bulletin-removable-top-squeaks-when-stowed-away-install-velcro-122.html)  
[corvette-service-bulletin-removable-top-squeaks-when-stowed-away-install-](#)  
[velcro-122.html](#)