

2015 - 2017 Corvette Z06: Service Bulletin: #17-NA-078: Information on Corvette and Camaro ZL1 Exhaust Tone During Wide Open Throttle while in Sport or Track Modes

#17-NA-078: Information on Corvette and Camaro ZL1 Exhaust Tone During Wide Open Throttle while in Sport or Track Modes - (Mar 17, 2017)

Subject:				Information on Corvette and Camaro ZL1 Exhaust Tone During Wide Open Throttle while in Sport or Track Modes			
Brand:	Model:	Model Year:		VIN:		Engine:	Transmi ssion:
		from	to	from	to		
Chevrol et	Camaro Corvett e	2015	2017			LT4	All

<i>Involved Region or Country</i>	North America and N.A. Export Regions
<i>Additional Options (RPOs)</i>	Equipped with 8 CYL, 6.2L Engine (RPO LT4)
<i>Condition</i>	Some customers may comment on that they hear a "pop" or "backfire" sound from the exhaust while

	performing a wide open throttle maneuver while in Sport or Track driving modes.
<i>Cause</i>	The exhaust sound heard during the wide open throttle maneuver is normal.
<i>Correction</i>	No repairs should be performed if there are no diagnostic codes, and the exhaust sound that the customer noticed goes away when the driver mode is selected to any other driver mode other than Sport or Track.

Parts Information

No parts are needed for this concern.

Customer Information

Please communicate to the customer this condition is a normal characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this bulletin.

<i>Version</i>	1
<i>Modified</i>	

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2015-2017->

[corvette-z06-service-bulletin-17-na-078-information-on-corvette-and-camaro-zl1-exhaust-tone-during-wide-open-throttle-while-in-sport-or-track-modes-1335.html](#)