


# **2017 - 2018 Corvette: Service Bulletin: 18197 Suspension Control Module Incorrect Calibration (US Only)**



**Date:** June 21, 2018

**Subject:** 18197 - Customer Satisfaction Program - Suspension Control Module Incorrect Calibration (US Only)

**Models:** 2017-2018 Chevrolet Corvette

Equipped with Suspension System-Ride, Handling, Performance (FE6)

**To:** All General Motors Dealers

General Motors is releasing Customer Satisfaction Program 18197 today. The total number of U.S. vehicles involved is approximately 26. Please see the attached bulletin for details.

**Condition:** Certain 2017 - 2018 model year Chevrolet Corvette vehicles, equipped with (RPO FE6) suspension system-ride, handling, and performance, may have an incorrect service calibration for the suspension control module, which may not provide the softer, higher quality ride improvement as intended.

**Correction:** Dealer will reprogram the suspension control module.

## **Customer Letter Mailing**

The customer letter mailing will begin on July 5, 2018.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2017-2018-corvette-service-bulletin-18197-suspension-control-module-incorrect-calibration-us-only-1395.html>