

1968 Corvette: Service Bulletin: Power Steering Bracket

Subject: Power Steering Bracket

Model and Year: 1968 Corvette with 427 cu. in. Engine

Source: Chevrolet Dealer Service Technical Bulletin

Bulletin Number: 68-T-46, Section IX

Date: Apr. 25, 1968

TO: AL CHEVROLET DEALERS

Some reports of power steering pump rackets cracking and/or breaking have been received on 1968 Corvettes equipped with 427 Cu. In. engine.

Effective in production since late March, a redesigned bracket has been used to correct the above condition.

In service when cracked or broken power steering pump brackets are encountered, they should be replaced with the following:

| PART NO. | DESCRIPTION | QUANTITY |
|----------|-------------|----------|
| 3946000 | Brace | 1 |
| 3946002 | Bracket | 1 |

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians

have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1968-corvette-service-bulletin-power-steering-bracket-183.html>