

2000 - 2004 Corvette: Service Bulletin: Twilight Sentinel/Automatic Headlamp Control Not Functioning Correctly or is Inoperative

Bulletin No: 03.08.42.012

Subject: Twilight Sentinel/Automatic Headlamp Control Not Functioning Correctly or is Inoperative (Reprogram BCM)

2000-2004 Chevrolet Corvette with Automatic Headlamp Control (RPO T82)

Condition

Some customers may comment that the twilight sentinel/automatic headlamp control delays turning on/turning off or is inoperative.

Correction

A procedure using the Tech 2® has been developed to reprogram the twilight sentinel feature within the BCM.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2000-2004-corvette-service-bulletin-twilight-sentinel-automatic-headlamp-control-not-functioning-correctly-or-is-inoperative-218.html>