

# 1969 Corvette: Engineering Service Letter: Speedometer Shaft Failure

**Subject:** Speedometer Shaft Failure

**Model and Year:** 1969 Corvette w/ 4-Speed Transmission

**Date:** NA

## UPC XII - ELECTRIC AND INSTRUMENTS

E.S.L.

**SPEEDOMETER SHAFT FAILURE** - 1969 Corvette w/ 4-Speed  
Transmission (#1106) (D.S.T.)

The failures have been attributed to kinking of the cable (transmission end) at time of installation. For interim 1969 Production, Engineering has released a new 5 inch longer cable and defined the routing to eliminate possibility of kinking.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1969-corvette-engineering-service-letter-speedometer-shaft-failure-24.html>