

1963 - 1965 Corvette: Engineering Service Letter: Air Gaps Between Corvette Folding Top

26 July 1, 2014 [Body and Trim](#) 0 713

Subject: Air Gaps Between Corvette Folding Top - Rear Bow Weatherstrip and Body Panel

Model and Year: 1963, 1964, 1965 Corvette

Date: Dec. 12, 1964

BODY - SECTION 1

ESL's

AIR GAPS BETWEEN CORVETTE FOLDING TOP - REAR BOW WEATHERSTRIP & BODY PANEL - (No. 55) 1963-64-65 Corvette

Problem is of weatherstrip not fitting tight to the body panel causing gaps at right and left side, permitting water and air entry.

Correction being worked out. Involves replacing seal with a newly designed seal which is not yet available.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1963-1965-corvette-engineering-service-letter-air-gaps-between-corvette-folding-top-26.html>