

# 2006 Corvette: Service Bulletin: 4L60-E, 4L65-E Automatic Transmission fluid Leak from Oil Pump or Bell Housing Area

**Subject:** 4L60-E, 4L65-E Automatic Transmission Fluid Leak from Oil Pump or Bell Housing Area (Remove Small Burrs on Torque Converter Hub, Pump Drive Slots and Replace Torque Converter Hub-to-Oil Pump Seal Assembly (243))

**Models:** 2006 Chevrolet Corvette with 4L60-E or 4L65-E Automatic Transmission (RPOs M30 or M32)

**Bulletin No:** 06-07-30-016

**Date:** July, 2006

Download PDF attachment below.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2006-corvette-service-bulletin-4l60-e-4l65-e-automatic-transmission-fluid-leak-from-oil-pump-or-bell-housing-area-276.html>