

1997 - 1998 Corvette: Service Bulletin: Inoperative Remote Keyless Entry System and/or Tire Pressure Monitor System

Subject: INOPERATIVE REMOTE KEYLESS ENTRY (RKE) SYSTEM AND/OR
TIRE PRESSURE MONITOR (TPM) SYSTEM (REPLACE RECEIVER)

Source: Chevrolet Dealer Technical Service Bulletin

Number: 83-90-14

Models: 1997-1998 Chevrolet Corvette

CONDITION:

SOME CUSTOMERS MAY COMMENT THAT THE REMOTE KEYLESS ENTRY (RKE) SYSTEM AND/OR THE TIRE PRESSURE MONITOR (TPM) SYSTEM IS INOPERATIVE IN TEMPERATURES BELOW 18 DEGREES CELSIUS (50 DEGREES FAHRENHEIT).

CAUSE:

SOME REMOTE DOOR/REAR COMPARTMENT RECEIVERS WERE BUILT WITH AN INTERNAL COMPONENT THAT MAY BE SUSCEPTIBLE TO COLD TEMPERATURES.

CORRECTION:

INSTALL NEW REMOTE DOOR/REAR COMPARTMENT RECEIVER, FOLLOWING THE PROCEDURE IN THE SERVICE MANUAL.

PARTS INFORMATION:

Part Number: 10422088

Description: RECEIVER, REMOTE DOOR/REAR COMPARTMENT LOCK

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

COPYRIGHT 1997 GENERAL MOTORS CORPORATION. ALL RIGHTS RESERVED

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1997-1998-corvette-service-bulletin-inoperative-remote-keyless-entry-system-and-or-tire-pressure-monitor-system-424.html>