1989 - 1990 Corvette: Service Bulletin: Improved Access to Inboard Seat Belt Buckle / New Extender

Subject: IMPROVED ACCESS TO INBOARD SEAT BELT BUCKLE/NEW

EXTENDER

Model and Year: 1989-90 CORVETTE WITH AQ9 SEATS

Source: Chevrolet Service Bulletin

Bulletin Number: 90-291-10 - (06/22/1990)

CONDITION:

To increase customer satisfaction a seat belt buckle extender has been released for service only, for use with AQ9 seats only.

CAUSE:

With seats in full forward and up position buckle may not be of optimum length.

CORRECTION:

If the customer should comment about this condition, a new seat belt extender, P/N 10175791 (Black only) is available from GMSPO at no charge to the customer.

NOTE: WHEN ORDERING THIS PART, IT IS MANDATORY THAT THE CUSTOMERS NAME AND THE VEHICLE IDENTIFICATION NUMBER BE INCLUDED WITH THE ORDERING INFORMATION. THE ORDERING FORM FOR THIS PURPOSE IS ATTACHED TO THIS BULLETIN. PLEASE COPY LOCALLY.

QUESTIONNAIRE

EXTENDED LENGTH SEAT BELT Passenger Cars, Light and Medium Truck Application

 In order to respond to your request for a seat belt extension, specific information must be supplied regarding the individual and vehicle involved.

		•	
	DEALERSHIP	APPLICANT'S	
COX NAI AODRES	E SS	ADDRESS	
ATTENTIO	DN:		
2. Vehic	cle Information of car or truck	k	
VE	CHICLE IDENTIFICATION NUMBER ((VIN) 800Y TYPE	
3. After Ident	r carefully reading the Bulleti dification Chart, fill in the E	in and instructions on the Belt Belt Latch Type Below:	
ŧ	ATCH TYPE		
4, Heast	urement Procedure for Front or	Rear Seat (In inches)	
(PLACE THE OCCUPANT IN THE SE RIDING IN THE CAR OR TRUCK .	EATING POSITION USED WHEN DRIVING	OR
	FRONT SEAT RE	EAR SEAT (Circle One)	
C	MEASURE FROM THE LEADING EDG EXTENDED TO THE FRONT EDGE O DIMENSION BELOW:	GE OF THE LATCH PLATE WITH THE BE OF THE BUCKLE (FIGURE 1) AND NOTE	LT FULLY
	HEASUREHENT	MEASUREMENT REQUIRED BUCKLE	LATCH PLATE
CAUTION: TO HELP LESSEN THE CHANCE AND/OR SEVERITY OF INJURY IN AN ACCIDENT, THE SEAT BELT EXTENSION MUST NOT BE USED BY ANYONE BUT THE PERSON FOR WHOM IT WAS MADE, OR IN ANY VEHICLE OTHER THAN THE VEHICLE FOR WHICH IT WAS MADE.			
	APPLICANT'S SIGNATURE	DATE	_
SUBHIT CO	PLETED APPLICATION TO:		

SERVICE PARTS OPERATIONS OF GENERAL HOTORS SEAT BELT EXTENDERS, SERVICE PARTS ASSISTANT CENTER P.O. BOX 1525 FLINT, HICHIGAN 48501 General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/1989-1990-corvette-service-bulletin-improved-access-to-inboard-seat-belt-buckle-new-extender-506.html