

1994 - 1995 Corvette: Service Bulletin: Door Glass Scratching (Replace outer seal in addition to glass)

55 July 2, 2014 [Body and Trim](#) 0 703

Bulletin Number: 53-10-17

Issued: 24-May-1995

Subject: Door Glass Scratching (Replace Outer Seal in Addition to Glass)

Models: 1994-95 Chevrolet Corvette

1994 VIN Breakpoints (Condition Start) - R5121349

1995 VIN Breakpoints (Condition Start) - S5111420

And all 1994 and 1995 ZR1 Models

Condition:

Some owners of the above vehicles may comment about scratches on door glass (depending on a number of factors including cleanliness, amount of glass cycles, etc.).

Correction:

When replacing the door glass for this condition on the above vehicles under warranty, also replace the outer seal strip. New seal strips are available from GMSPO under the following part numbers:

P/N	DESCRIPTION
10245645	Seal Strip (Left Side)
10245646	Seal Strip (Right Side)

Important: When removing rivets, care should be taken to capture all loose pieces to prevent rattles.

Part Information: Parts are expected to be available on 5/22/95 from GMSPO.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1994-1995-corvette-service-bulletin-door-glass-scratching-replace-outer-seal-in-addition-to-glass-55.html>