

# 1965 Corvette: Engineering Service Letter: Dying on Quick Right Turns

**Subject:** Dying on Quick Right Turns

**Model and Year:** 1965 Corvettes Equipped with 365 HP - 327 CU IN Engine and Holley Carburetor

**Source:** Chevrolet Engineering Service Letter - Service Parts Change

**Number:** T.N. #7, Section VI

**Date:** June 30, 1965

## Miscellaneous

### **Corvette with 365 HP - 327 CU IN Engine and Holley Carburetor Dying on Quick Right Turns**

Condition can be corrected by installing the following Holley parts:

Floats: P/N 16R - 429A

Needles & Floats: P/N 18R - 96A

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1965-corvette-engineering-service-letter-dying-on-quick-right-turns-732.html>