# 1955 - 1957 Corvette: Service Bulletin: V-8 Distributor Chart

**Subject:** V-8 Distributor Chart
**Model and Year:** 1955 Thru 57 Passenger Cars and Trucks
**Source:** Chevrolet Service Bulletin
**Bulletin Number:** DR #291, Section VIy, April 26, 1957

**TO:** ALL CHEVROLET DEALERS

Chart on page 2 of this bulletin lists V-8 Distributors used on 1955 thru 57 Passenger Cars and Trucks with spark setting @ idle.

The numbers stamped on the distributor plates are used as a means of identification only. In some instances the service number and numbers on plats are identical.

Numbers on plats should not be used as a basis for ordering service parts.

Spark Setting

To eliminate confusion all spark settings are now to be made at idle only.

Markings on the ignition timing tab attached to the front end cover are in 2 degree increments from the "0" marking.

In heavy duty truck operations, where spark plug burning and pre-ignition are problems, remove the vacuum spark advance.

## V-8 DISTRIBUTORS

| MODELS | NUMBER ON DIST. PLATE - | SERVICE PART NO. | SPARK SETTING @ IDLE |
|---|---|---|---|
| 1955 - All 265 cu.in. (Except Corvette) | 1110847 | 1110847 | 4° BTDC |
| 1955 Corvette (265 cu.in.) | 1110855 | 1110855 | 4° BTDC |
| *1956 Pass.(2 Bbl.) & 3-4-5 6000 Truck (265 cu.in.) | 1110847 | 1110847 | 4° BTDC |
| 1956 7-8000 (265 cu.in.) 5-6000 w/Gov. | 1112330 | 1112330 | 48 BTDC |
| 1956 Pass. (265.cu.in.) (4 Bbl.) | 1110866 1110869 1110878 | 1110869 | 4° BTDC |
| 1956 Pass. Dual 4 Bbl. (265 cu.in.) | 1110872 1110879 | 1110879 | 8° BTDC (Do not Exceed 12° BTDC) |
| 1956 Corvette (265 cu.in.) | 1110872 1110879 | 1110879 | 4° BTDC |
| 1956 (322 cu. in.) | 1112331 | 1112343 | 4° BTDC |
| 1957 Pass.(2 Bbl.) & 3-4000 (265 cu.in.) | 1110874 | 1110874 | 4° BTDC |
| 1957 Pass.(4 Bbl.)(283 cu. in.) | 1110890 | 1110890 | 4° BTDC |
| 1957 Pass.(2 x 4 Bbl.)(283 cu.in.) | 1110891 | 1110891 | 12° BTDC (do not Exceed 14° BTDC) |
| 1957 Pass. & Corvette Fuel Injection(283 cu.in.) | 1110889 1110905 | #1110905 | 4° BTDC (Do not Exceed 8° BTDC) |
| | 1110906 | $1110906 | 12° BTDC (Do not Exceed 14° BTDC) |
| 1957 5-6-7-8000 (2 Bbl.)(283 cu.in.) | 1112349 | 1112349 | 4° BTDC |
| 1957 (2 Bbl.) (322 cu.in.) | 1112331 1112343 | 1112343 | 4° BTDC |
| 1957 (4 Bbl.) 5-6-7-8000 (283 Cu.in.) | 1112350 | &1112349 | 4° BTDC |
| 1957 (4 Bbl.) (322 cu.in.) | 1112707 | &1112343 | 4° BTDC |
| 1957 Corvette(4 Bbl.)(283 cu.in) | 1110891 | 1110891 | 4° BTDC |

* Except vacuum spinner governor on 5000-6000.
& This substitution accomplished by resetting spinner valve.
$ Standard highlift camshaft with automatic transmission.
# Duntov(High performance camshaft)with manual transmission.

Both 1110906 & 905 must be ordered on Special Order through Central Office Parts & Accessory Department.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved.**

Online URL:
https://www.corvetteactioncenter.com/tech/knowledgebase/article/1955-1957-corvette-service-bulletin-v-8-distributor-chart-780.html