

1989 - 1990 Corvette: Recall Notice: Product Campaign 90C09 Inoperative Parking Brake



Subject: Product Campaign 90C09 and 90C09 (a) Inoperative Parking Brake

Model and Year: 1989 - 1990 Corvette

Source: Chevrolet Dealer Product Campaign Bulletin

Bulletin No: 90C09 and 90C09(a)

Section: 5

Date: January 1990 and March 1990



CHEVROLET MOTOR DIVISION
General Motors Corporation



Chevrolet Dealer Product Campaign Bulletin

SUPPLEMENT
90C09 (a)

Number: 5

Section:
March, 1990

Date:

Subject: PRODUCT CAMPAIGN 90C09 (a)
INOPERATIVE PARKING BRAKE

Attn: Service Manager

Model and Year: 1989-90 CHEVROLET CORVETTE

To: All Chevrolet Dealers

This bulletin revises the VEHICLES INVOLVED and OWNER NOTIFICATION sections of Chevrolet Product Campaign Bulletin 90C09, dated January, 1990. Specifically, certain 1989 Chevrolet Corvettes have been added to this campaign.

VEHICLES INVOLVED

Involved are certain 1989-90 Chevrolet Corvette model vehicles built within the following VIN breakpoints:

MODEL/YEAR	PLANT	FROM	THROUGH	OPTION
Y 1989	Bowling Green	K5102000	K5110724	L98 Engine
Y 1989	Bowling Green	K5122004	K5126328	L98 Engine
Y 1990	Bowling Green	L5100001	L5100887	L98 Engine
Y 1990	Bowling Green	L5800001	L5800120	LT5 Engine

Involved vehicles have been identified by Vehicle Identification Number Computer Listings. Computer listings contain the complete Vehicle Identification Number, owner name and address data, and are furnished to involved dealers with the campaign bulletin. Owner name and address data furnished will enable dealers to follow-up with owners involved in this campaign.

These listings may contain owner names and addresses obtained from State Motor Vehicle Registration Records. The use of such motor vehicle registration data for any other purpose is a violation of law in several states. Accordingly, you are urged to limit the use of this listing to the follow-up necessary to complete this campaign. Any dealer not receiving a computer listing with the campaign bulletin has no involved vehicles currently assigned.

Denotes Change



CHEVROLET MOTOR DIVISION
General Motors Corporation



Chevrolet Dealer Product Campaign Bulletin

90C09

Number: 5

Section:
January, 1990

Date:

Subject: PRODUCT CAMPAIGN 90C09
INOPERATIVE PARKING BRAKE

Attn: Service Manager

Model and Year: 1990 CHEVROLET CORVETTE

TO: ALL CHEVROLET DEALERS

General Motors has determined that certain 1990 Chevrolet Corvette model vehicles may exhibit an inoperative parking brake upon attempted engagement. This is due to the cable button pulling through and separating from the nylon reel resulting in an inoperable parking brake. This separation is a time related condition dependent on the number of parking brake applications, and occurs only upon parking brake application, not under sustained load conditions.

To correct this condition, a new parking brake lever assembly will be installed on the involved vehicles.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Chevrolet Motor Division. Some owners will receive letters addressing more than one campaign on their vehicle (see copies of owner letters included with this bulletin) as shown in the chart below.

<u>VIN Range</u>	<u>Campaigns Addressed In Owner Letters</u>
L5800001 - L5800120	90C07 / 90C09 / 90C10
L5100001 - L5100887	90C07 / 90C09

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners, regardless of mileage, age of vehicle, or ownership, from this time forward.

Whenever a vehicle subject to this campaign is taken into your new or used vehicle inventory, or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle.

Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer, and arrangements made to make the required correction according to instructions contained in this bulletin.

PARTS INFORMATION

Parts, when required, are to be obtained from General Motors Service Parts Operations (GMSPO). To ensure parts will be obtained as soon as possible, they should be ordered from GMSPO on a "C.I.O." order with no special instruction code, but on an advise code (2).

<u>Part Number</u>	<u>Description</u>	<u>Quantity/ Vehicle</u>
10097695	Parking Brake Lever Assembly	1

SERVICE PROCEDURE

1. Replace parking brake lever assembly referring to Section 5 of the 1990 Corvette Service Manual.
2. Install Campaign Identification Label.

CAMPAIGN IDENTIFICATION LABEL

Each vehicle corrected in accordance with the instructions outlined in this bulletin will require a "Campaign Identification Label". Each label provides a space to include the five (5) digit dealer code of the dealer performing the campaign service. This information may be inserted with a typewriter or a ball point pen.



Each "Campaign Identification Label" is to be located on the radiator core support in an area which will be visible when the vehicle is brought in for periodic servicing by the owner.

Apply "Campaign Identification Label" only on a clean dry surface.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1989-1990-corvette-recall-notice-product-campaign-90c09-inoperative-parking-brake-1095.html>