

1967 Corvette: Engineering Service Letter Note: Steering Shaft Upper Retaining Ring Removal on Telescoping Columns

Subject: Steering Shaft Upper Retaining Ring Removal on Telescoping Columns (#608) (T.N.)

Model and Year: 1967 Corvair, 1967 Corvette

Source: Chevrolet Engineering Service Letter Note

Page Number: NA

Date: February - March 1967

The subject retaining ring is a two winding spiral type instead of the snap type as shown in the Chassis Service Manual, Section 9, Item 16, Fig. 54; and the Corvette Manual, Section 9, Item 26, Fig. 9.

The retaining ring can be removed using a small screwdriver. Place the blade of the screwdriver under the end of the ring and pry out and up while rotating the shaft. Install a new ring when reassembling.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1967-corvette-engineering-service-letter-note-steering-shaft-upper-retaining-ring-removal-on-telescoping-columns-1106.html>