

# 1978 - 1980 Corvette: Service News: Speedometer System Noise Diagnosis and Repair

---

**Subject:** Speedometer System Noise Diagnosis and Repair

**Model and Year:** 1978 - 1980 Corvette - All Vehicles

**Source:** Chevrolet Service News

**Page Number:** NA

**Date:** Part E. , Volume 52-3, May - June 1980


This speedometer system noise diagnosis and repair chart is not present in the factory shop manuals for 1980 Corvettes and is also applicable to 1978 - 1979 Corvettes.

## BODY AND CHASSIS ELECTRICAL

### Speedometer System Noise Diagnosis and Repair — All Vehicles

Refer to diagnosis chart on Page 19 for speedometer system diagnosis and repair.

#### SPEEDOMETER SYSTEM NOISE — DIAGNOSIS AND REPAIR • •



• COLD TEMPERATURE CONDITION WILL REQUIRE COLD SOAK TO DUPLICATE NOISE.

• IF REPLACING A COMPONENT DOES NOT ELIMINATE THE NOISE, REINSTALL THE ORIGINAL COMPONENT.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1978-1980-corvette-service-news-speedometer-system-noise-diagnosis-and-repair-1188.html>