

1968 Corvette: Service Bulletin: Condenser and Receiver-Dehydrator Removal

This General Motors Dealer Service Information Bulletins comes from General Motors Products of Canada Limited. Below is a revised procedure and shop manual update for removal the condenser and receiver-dehydrator on 1968 Corvettes:

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1968-corvette-service-bulletin-condenser-and-receiver-dehydrator-removal-1228.html>