

2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 13, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 13, 2016)

Subject: Loss of Radio Controls and/or HVAC Controls

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2016			All	All

<i>Involved Region or Country</i>	North America and all N.A.Export Regions
<i>Condition</i>	<p>Some customers may comment on a loss of function with the Radio/HVAC Interface Control Module (ICS) after ignition 'on' cycle.</p> <p>The condition will exhibit intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle.</p>
<i>Cause</i>	This may be caused by incorrect software/utility file level.

Correction

If you encounter a vehicle with the above concern, reprogram the radio control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-13-2016-1278.html>