

2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

Subject: Loss of Radio Controls and/or HVAC Controls

Brand:	Model:	Model Year:	VIN:	Engine:	Transmission:
		from	to	from	to
Chevrolet	Corvette	2014	2016	All	All

Involved Region or Country

North America and all N.A.Export
Regions

Condition

Some customers may comment on a
loss of function with the
Radio/HVAC Interface Control
Module (ICS) after ignition 'on'
cycle.

The condition will exhibit
intermittent characteristics, where
the loss of function will discontinue
after an additional ignition cycle.

Cause

This may be caused by incorrect
software/utility file level.

Correction

If you encounter a vehicle with the above concern, reprogram the radio

control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-29-2016-1287.html>