

# 2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

## #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

<b>Subject:</b>		Loss of Radio Controls and/or HVAC Controls					
Brand:	Model:	Model Year:		VIN:		Engine:	Transmi
		from	to	from	to		ssion:
Chevrolet	Corvette	2014	2016			All	All

### *Involved Region or Country*

North America and all N.A.Export  
Regions

### *Condition*

Some customers may comment on a  
loss of function with the  
Radio/HVAC Interface Control  
Module (ICS) after ignition 'on'  
cycle.

The condition will exhibit  
intermittent characteristics, where  
the loss of function will discontinue  
after an additional ignition cycle.

### *Cause*

This may be caused by incorrect  
software/utility file level.

### **Correction**

If you encounter a vehicle with the above concern, reprogram the radio

control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-29-2016-1287.html>