

2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

Subject:	Loss of Radio Controls and/or HVAC Controls					
Brand:	Model:	Model Year:	VIN:	Engine:	Transmi	
		from	to	from	to	ssion:
Chevrolet	Corvette	2014	2016		All	All
<i>Condition</i>	<p>et</p> <p>North America and all N.A. Export Regions</p> <p>Some customers may comment on a loss of function with the Radio/HVAC Interface Control Module (ICS) after ignition 'on' cycle.</p>					
<i>Cause</i>	<p>The condition will exhibit intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle. This may be caused by incorrect software/utility file level.</p>					
<i>Correction</i>	<p>If you encounter a vehicle with the above concern, reprogram the radio</p>					

control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-29-2016-1287.html>