

## 2015 - 2018 Corvette : Service Bulletin: #17-NA-072: Information on Installation of Stage One and Two Rear Wicker Bills on Spoiler - (Mar 21, 2017)

### #17-NA-072: Information on Installation of Stage One and Two Rear Wicker Bills on Spoiler - (Mar 21, 2017)


<b>Subject:</b>	Information on Installation of Stage One and Two Rear Wicker Bills on Spoiler
-----------------	---

This Bulletin replaces PI1478A. Please discard PI1478A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2015	2018			All	All

<i>Involved Region or Country</i>	North America and N.A. Export Regions
<i>Additional Options (RPOs)</i>	Equipped with RPO CFV or CFZ

**Information**



During the installation of the rear wicker bills that are fastened on the rear spoiler, some technicians may revert to the use of power tools to tighten the fasteners.



The use of power tools should not be used due to the fact that this could lead to damage to the fasteners and/or the spoiler.

When installing the wicker bills onto the vehicle, it is recommended to hand start the fasteners before using the correct hand tools to torque the fasteners to the proper torque specifications.

Damage to the fasteners or the spoiler should not be submitted under warranty as the parts are dealer installed components during the pre-delivery process.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2015-2018-corvette-service-bulletin-17-na-072-information-on-installation-of-stage-one-and-two-rear-wicker-bills-on-spoiler-mar-21-2017-1342.html>