

2019 Corvette ZR1: Service Bulletin:

#19-NA-042: Yellow Tint to ZR1s Hood and Engine Cover Exposed Carbon Fiber Parts

#19-NA-042: Yellow Tint to ZR1s Hood and Engine Cover Exposed Carbon Fiber Parts - (Feb 28, 2019)

Subject: Yellow Tint to ZR1's Hood and Engine Cover Exposed Carbon Fiber Parts

Brand:	Model:	Model Year: from	to	VIN: from	to	Engine:	Transmis sion:
Chevrolet	Corvette ZR1	2019	2019			All	All

Involved Region or Country

North America and N.A. Export Regions

Condition

Some customers may comment that the ZR1's exposed carbon fiber hood parts appear to have a yellow tint appearance when compared to other carbon fiber parts.

Cause

The cause of the condition may be that the carbon fiber hood and engine cover use a different impregnated carbon fiber resin, which is more heat resistant. The different resin may

Correction

cause a color shift; and the lighting source and direction of view will sometimes highlight this color shift. There is no problem with the paint application on these carbon fiber parts, and NO repair attempts should be made to change the color of the parts.

Version

1

Modified

Released February 28, 2019

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2019-corvette-zr1-service-bulletin-19-na-042-yellow-tint-to-zr1s-hood-and-engine-cover-exposed-carbon-fiber-parts-1408.html>