

2019 Corvette ZR1: Service Bulletin: #19-NA-042: Yellow Tint to ZR1s Hood and Engine Cover Exposed Carbon Fiber Parts

#19-NA-042: Yellow Tint to ZR1s Hood and Engine Cover Exposed Carbon Fiber Parts - (Feb 28, 2019)

Subject: Yellow Tint to ZR1's Hood and
Engine Cover Exposed Carbon Fiber
Parts

Brand:	Model:	Model Year: from	to	VIN: from	to	Engine:	Transmis sion:
Chevrolet	Corvette ZR1	2019	2019			All	All

Involved Region or Country

North America and N.A. Export
Regions

Condition

Some customers may comment that
the ZR1's exposed carbon fiber hood
parts appear to have a yellow tint
appearance when compared to other
carbon fiber parts.

Cause

The cause of the condition may be that
the carbon fiber hood and engine
cover use a different impregnated
carbon fiber resin, which is more heat
resistant. The different resin may

Correction

cause a color shift; and the lighting source and direction of view will sometimes highlight this color shift. There is no problem with the paint application on these carbon fiber parts, and NO repair attempts should be made to change the color of the parts.

Version

1

Modified

Released February 28, 2019

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2019-corvette-zr1-service-bulletin-19-na-042-yellow-tint-to-zr1s-hood-and-engine-cover-exposed-carbon-fiber-parts-1408.html>