2020 - 2021 Corvette: Service Bulletin: #PIC6407C: Amplifier Part Restriction - (Sep 21, 2020)

#PIC6407C: Amplifier Part Restriction - (Sep 21, 2020)

Subject:				Amplific	er Part Ro	estriction	1
Brand :	Model:	Model Year :		VIN:		Engine: Transmi	
		from	to	from	to		ssion:
Cadillac	CT4	2020		All	All	All	All
Cadillac	CT5	2020		All	All	All	All
Chevrole	Corvette	2020 - 202	21	All	All	All	All
t							

Involved Region or Country

Condition

As part of our ongoing continuous improvement we have placed the Amplifier used in the 2020 Cadillac CT4, CT5 and Chevrolet Corvette on restriction. If you believe a new module is needed, contact the PQC. Please have the part number available prior to contacting PQC.

Cause

North America

As part of our ongoing continuous improvement we have placed the Amplifier used in the 2020 Cadillac CT4, CT5 and Chevrolet Corvette on restriction. If you believe a new module is needed, contact the PQC.

Please have the part number available prior to contacting PQC.

Root Cause Analysis

Correction

Please contact the (PQC) by opening a new case via Dealer Case Management (DCM). From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Then, in Global Connect click on the Support/Chat tab, TAC-PQC Tab, PQC - Parts Restrictions Templates to Download the appropriate PQC - Parts Restrictions Template and save a copy to your computer. You can attach a copy of the template to your PQC Case.

Note: (Do Not clear any DTCs prior to contacting the PQC)

Parts Information

Part Number	Description	Qty
84798070 or	Amplifier CT4, and	1
84978871	CT5 (UQG - 8	
	Channel)	
84825170 or	Amplifier	1
84941695 (2020) or	Corvette (UQH - 16	
84930047 (2021)	Channel)	
84825171 or	Amplifier Corvette	1
84941694 (2020) or	(UQS - 10 Channel)	
84930046 (2021)		
84833560 or	Amplifier CT5 (UQP -	1
84886772	12 Channel)	
84886773	Amplifier CT4 (UQS -	1
	10 Channel)	

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation Description Labor T

3421200 Radio Speaker Use Published Labor

Amplifier Time

Replacement

Version 4

Modified 03/16/2020 – Created on.

04/21/2020 - Updated Part

Numbers.

05/29/2020 - Updated Part

Numbers.

09/21/2020 - Updated Part

Numbers.

Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-2021-corvette-service-bulletin-pic6407c-amplifier-part-restriction-sep-21-2020-1443.html