

2020 Corvette: Service Bulletin: #20-NA-214: Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down - (Oct 30, 2020)

#20-NA-214: Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down - (Oct 30, 2020)

Subject: Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down

Brand:	Model:	Model Year:	VIN:	Engine:	Transmis		
		from	to		sion:		
Chevrolet	Corvette	2020	2020	—	—	All	All

Involved Region or Country
Condition

North America, Saudi Arabia
Some customers may comment that when they are operating either door glass up or down, the window may intermittently auto reverse.

Cause

The cause of the condition may be that the door window may be out of adjustment.

Correction

Note: DO NOT replace the window motor, or window regulator, without making the door window adjustment first.

Adjust the front side door window.
Refer to *Front Side Door Window Adjustment* in SI.

Parts Information

No parts are normally required for this repair.

Version

1

Modified

Released October 30, 2020

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-corvette-service-buletin-20-na-214-information-on-front-side-door-window-intermittently-auto-reverses-when-going-up-or-down-oct-30-2020-1468.html>