

# 2005 - 2007 Corvette: Service Bulletin: Power Steering Shudder or Vibration at Idle

**Date:** October 18, 2006

**Bulletin #:** #06-02-32-012B

**Subject:** Power Steering Shudder or Vibration at Idle (Replace Power Steering Inlet (Pressure) Hose)

**Models:** 2005-2007 Chevrolet Corvette with Automatic Transmission

## **Condition**

Some customers may comment on a shudder/vibration while rotating the steering wheel at idle. This vibration can be very minor to where it is only felt in the steering wheel or major enough to notice a slight shake in the interior components. Rougher road surfaces can increase the intensity as it increases the drag against the wheels as they attempt to turn. Slightly raising the engine idle should eliminate the vibration.

## **Cause**

At idle, turning the wheels causes the steering pressures to raise high enough to cause a load on the engine. The load is great enough to cause the idle to become rough and it can be felt in the vehicle.

## **Correction**

Replace the power steering inlet (pressure) hose with the part number listed below.

For vehicles with either FE1 or FE2 suspension, a retaining clip, P/N 88967174, is also required. After installing the new hose, attach the clip to the hose just before the crimp, as shown. Secure the other end of the clip to the

existing power steering return line.

15903239 (FE1/FE2 Suspension) Power Steering Inlet (Pressure) Hose

15903240 (FE3/FE4 Suspension) Power Steering Inlet (Pressure) Hose

88967174 Clip FE1/FE2 Suspension

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserve**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2007-corvette-service-bulletin-power-steering-shudder-or-vibration-at-idle-153.html>