

# 2005 - 2009 Corvette: Service Bulletin: Snap, Pop or Rattle Noise From Lift Off Roof Panel While Driving

**Bulletin #:** 08.08.67.013A

**Subject:** Snap, Pop or Rattle Noise From Lift Off Roof Panel While Driving (Replace Front Lift Off Roof Panel Handles and Lube)

**Models:** 2005-2009 Chevrolet Corvette with Removable Clear Roof Panel (RPO CC3), Removable Sun Roof Panel (RPO CF7) or Dual Removable Roof Panels (RPO C2L)

## **Condition**

Some customers may comment on a snap, pop or rattle noise coming from the lift off roof panel while driving.

## **Cause**

This condition may be caused by the nylon roller inside the left and/or right front roof panel latching handle becoming loose and causing the roller to move on the pin, creating the noise.

## **Correction**

Replace the left and right front lift off roof panel handles (1) and lube. Refer to Roof Lift Off Panel Front Latch Handle Replacement in SI. The updated handles have a new design ramp insert in place of the nylon roller.

Technicians are to apply GM Super Lube® with PTFE, P/N 12371287 (in Canada, P/N 10953437) to both sides (left and right) at the following areas:

Apply GM Super Lube® around the entire guide pin ball (1) on the roof panel.

Apply GM Super Lube® inside the "pocket" of the stainless steel track (1).

19206591

Handle, Roof Lift Off Panel - Left

19206592

Handle, Roof Lift Off Panel - Right

12371287 (US)

GM Vehicle Care Super Lube® with PTFE

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserve**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2009-corvette-service-bulletin-snap-pop-or-rattle-noise-from-lift-off-roof-panel-while-driving-154.html>