

2007 Corvette: Service Bulletin: Instrument Panel (I/P), Body and General Wiring Harness Repair

Service Bulletin #: 06-06-45-004

Date: May 2006

Subject: Instrument Panel (I/P), Body and General Wiring Harness Repair

Model(s):

2007 and Prior GM Cars and Trucks

2003-2007 HUMMER H2

2006 - 2007 HUMMER H3

Attached below is the PDF for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=199>