

# 2007 Corvette: Service Bulletin: Dead Battery, Reprogram RCDLR

**Bulletin Number:** 07.06.03.001

## Condition

Some customers may comment on a dead battery after the vehicle has been parked for a extended period of time. Typically, the battery will last approximately two weeks.

## Cause

A software anomaly within the remote control door lock receiver (RCDLR) causes an additional 30 mA draw on the battery when passive locking is enabled and the vehicle is parked.

## Correction

Reprogram the remote control door lock receiver.

On Corvette models, prior to reprogramming, remove the Radio/S-Band/VICS 15-amp fuse from the I/P electrical center (passenger side).

**Online URL:**

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2007-corvette-service-bulletin-dead-battery-reprogram-rcdlr-233.html>