

# 2007 Corvette: Service Bulletin: Diagnostic Tips for Automatic Transmission DTC P0756, Second, Third, Fourth Gear Start

**Service Bulletin #:** 01-07-30-036F

**Date:** February 2006

**Subject:** Diagnostic Tips for Automatic Transmission DTC P0756, Second, Third, Fourth Gear Start

**Model(s):**

2007 and Prior Passenger Cars and Light Duty Trucks

2003-2007 Hummer H2

2006-2007 Hummer H3

2005-2007 Saab 9-7X

with 4L60-E, 4L65-E or 4L70-E Automatic Transmission (RPOs M30, M32 or M70)

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2007-corvette-service-bulletin-diagnostic-tips-for-automatic-transmission-dtc-p0756-second-third-fourth-gear-start-269.html>