


# **2000 - 2006 Corvette: Service Bulletin: Diagnostic Information on Diagnostic Trouble Code (DTC) P0894 and P1870**



**Service Bulletin #:** 02-07-30-001D

**Date:** December 2005

**Subject:** Diagnostic Information on Diagnostic Trouble Code (DTC) P0894 and P1870

**Model(s):**

2000-2006 GM Passenger Cars and Light Duty Trucks

2003-2006 Hummer H2

2006 Hummer H3

2005-2006 Saab 9-7X

with 4L60E or 4L65-E Automatic Transmission

Attached below is the PDF for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2000-2006-corvette-service-bulletin-diagnostic-information-on-diagnostic-trouble-code-dtc-p0894-and-p1870-270.html>