

2006 Corvette: Service Bulletin: Diagnosis of Cracked or Broken Transmission Case

Service Bulletin #: 02-07-30-024B

Date: August 2005

Subject: Diagnosis of Cracked or Broken Transmission Case

Model(s):

2006 and Prior Cars and Light Duty Trucks

2006 and Prior Hummer H2

2006 Hummer H3

2005-2006 Saab 9-7X

with 4L60/4L60-E/4L65-E or 4L80-E/4L85-E or Allison Series 1000 Automatic Transmission

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2006-corvette-service-bulletin-diagnosis-of-cracked-or-broken-transmission-case-271.html>