

# **2005 (Canadian Corvettes Only): Recall 04096: Incorrect Air Bag Off Indicator Assembly**

**Recall #: 04096**

## **Incorrect Air Bag Off Indicator Assembly**

### **2005 Chevrolet Corvette - Canada Only Vehicles**

#### **Condition**

Certain 2005 model year Chevrolet Corvettes were built with an incorrect air bag off indicator assembly located on the centre console. The indicator assembly that was used included text to indicate the on and the off positions rather than the international symbol.

#### **Correction**

Dealers are to replace the air bag off indicator assembly.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-canad>

[ian-corvettes-only-recall-04096-incorrect-air-bag-off-indicator-assembly-348.html](#)