

1998 - 2001 Corvette Convertible: Service Bulletin: Paint Wear Through at Fifth Bow (Replace Seal)

Source: Chevrolet Dealer Service Bulletin

Number: 02-08-111-001

Date: 02/05/2002

Subject: Paint Wear Through at Fifth Bow (Replace Seal)

Model Year: 1998-2001 Chevrolet Corvette

Condition

Some customers may comment that the paint around the tonneau cover at the 5th bow is wearing through.

Correction

Replace the 5th bow seal using the following procedure:

1. Position the folding top with bows 1 & 5 in the up position.
2. Open the stowage lid and position the seats forward.
3. Close the top (with the stowage lid open).
4. Remove the right and left hand weatherstrip retaining nuts.
5. Position the folding top with bows 1 & 5 in the up position.
6. Remove the weatherstrip from the vehicle.
7. Install weatherstrip to #5 bow.
8. Install the right and left hand weatherstrip retaining nuts.
9. Position the folding top with bows 1 & 5 in the up position and reposition the seats.
10. Close the stowage lid and folding top.

Parts Information

Part Number	Description
10319827	Weatherstrip ASM-F/Top RR

Parts are currently available from GMSPO.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
B3160	Seal, No. 5 Bow- Replace	0.6 hr

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1998-2001-corvette-convertible-service-bulletin-paint-wear-through-at-fifth-bow-replace-seal-460.html>