

# 1989 - 1990 Corvette: Service Bulletin: Improved Access to Inboard Seat Belt Buckle / New Extender

**Subject:** IMPROVED ACCESS TO INBOARD SEAT BELT BUCKLE/NEW  
EXTENDER

**Model and Year:** 1989-90 CORVETTE WITH AQ9 SEATS

**Source:** Chevrolet Service Bulletin

**Bulletin Number:** 90-291-10 - (06/22/1990)

## **CONDITION:**

To increase customer satisfaction a seat belt buckle extender has been released for service only, for use with AQ9 seats only.

## **CAUSE:**

With seats in full forward and up position buckle may not be of optimum length.

## **CORRECTION:**

If the customer should comment about this condition, a new seat belt extender, P/N 10175791 (Black only) is available from GMSPO at no charge to the customer.

**NOTE: WHEN ORDERING THIS PART, IT IS MANDATORY THAT THE CUSTOMERS NAME AND THE VEHICLE IDENTIFICATION NUMBER BE INCLUDED WITH THE ORDERING INFORMATION. THE ORDERING FORM FOR THIS PURPOSE IS ATTACHED TO THIS BULLETIN. PLEASE COPY LOCALLY.**

QUESTIONNAIRE  
EXTENDED LENGTH SEAT BELT  
Passenger Cars, Light and Medium Truck Application

1. In order to respond to your request for a seat belt extension, specific information must be supplied regarding the individual and vehicle involved.

DEALERSHIP	APPLICANT'S
CODE _____	NAME _____
NAME _____	ADDRESS _____
ADDRESS _____	_____
ATTENTION: _____	

2. Vehicle Information of car or truck

VEHICLE IDENTIFICATION NUMBER (VIN) \_\_\_\_\_  
YEAR \_\_\_\_\_ BODY TYPE \_\_\_\_\_

3. After carefully reading the Bulletin and instructions on the Belt Identification Chart, fill in the Belt Latch Type Below:

LATCH TYPE \_\_\_\_\_


4. Measurement Procedure for Front or Rear Seat (In inches)

- 0 PLACE THE OCCUPANT IN THE SEATING POSITION USED WHEN DRIVING OR RIDING IN THE CAR OR TRUCK .....

*FRONT SEAT      REAR SEAT* (Circle One)

- 0 MEASURE FROM THE LEADING EDGE OF THE LATCH PLATE WITH THE BELT FULLY EXTENDED TO THE FRONT EDGE OF THE BUCKLE (FIGURE 1) AND NOTE DIMENSION BELOW:

MEASUREMENT \_\_\_\_\_



\*\*\*\*\*ATTENTION APPLICANT\*\*\*\*\*  
CAUTION: TO HELP LESSEN THE CHANCE AND/OR SEVERITY OF INJURY IN AN ACCIDENT, THE SEAT BELT EXTENSION MUST NOT BE USED BY ANYONE BUT THE PERSON FOR WHOM IT WAS MADE, OR IN ANY VEHICLE OTHER THAN THE VEHICLE FOR WHICH IT WAS MADE.

\_\_\_\_\_  
APPLICANT'S SIGNATURE

\_\_\_\_\_  
DATE

SUBMIT COMPLETED APPLICATION TO:

SERVICE PARTS OPERATIONS OF GENERAL MOTORS  
SEAT BELT EXTENDERS,  
SERVICE PARTS ASSISTANT CENTER  
P. O. BOX 1525  
FLINT, MICHIGAN 48501

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1989-1990-corvette-service-bulletin-improved-access-to-inboard-seat-belt-buckle-new-extender-506.html>