

1986 - 1987 Corvette: Service Bulletin: Clutch Master Cylinder Push Rod Bushing

Subject: Clutch Master Cylinder Push Rod Bushing

Model Year: 1986 - 1987 Corvette with Manual Transmission

Source: Chevrolet Dealer Service Bulletin

Bulletin No: 87-114, Section 7C

Date: April, 1987

TO: ALL CHEVROLET DEALERS


Some 1986 or 1987 Corvettes with manual transmissions may experience inadequate retention of the clutch master cylinder push rod attachment.

If the condition exists, remove the plastic bushing from the master cylinder push rod and replace with the following service parts. (Refer to Figure 1):

| DESCRIPTION | PART NUMBER |
|-------------|-------------|
| Bushing | 14080233 |
| Flat Washer | 120395 |
| Retainer | 148149 |

Use applicable Labor Time and Operation Number.

Chevrolet Motor Division
General Motors Corporation



Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1986-1987-corvette-service-bulletin-clutch-master-cylinder-push-rod-bushing-904.html>