

1960 - 1961 Corvette: Service Bulletin: Delco Radio Service Parts

Below is a copy of a Delco Radio Service Bulletin dated 11-28-1960 showing all of the changes between the 1960 Corvette radio and the 1961 Corvette radio with their replaced part numbers. The only "new" parts on the 1961 Corvette are shown with an asterisk.



Delco Radio

SERVICE Bulletin

Section 2
Chevrolet 1961
Corvette
Model 985003
Date 11-28-60 (Revised)
Page 1
File In:
GM Autoradio Manual


**SUBJECT: SERVICE INSTRUCTIONS - CORVETTE MODEL 985003
WITH AUTOMATIC TUNING**

GENERAL

Mounting—All 1961 Corvette Cars.

SERVICE INFORMATION

This radio is identical to model 3748611 with the exception of the following changes in service parts.



MODEL 985003

SERVICE PARTS LIST

Illus. No.	Service Part No.	Description
ELECTRICAL PARTS		
Coils		
5	1221151	Oscillator, tuning
8	7274342	Choke, input filter
Capacitors		
33	7271557	1000 mfd., 1 volt, electrolytic
Resistors		
40	1214563	2.2 megohm, ½ watt
41	1213283	1.5 megohm, ½ watt
42	1213252	10,000 ohms, ½ watt
43	1213273	150,000 ohms, ½ watt
44	1213283	1.5 megohm, ½ watt
45	1213488	680,000 ohms, ½ watt
46	1213845	33,000 ohms, ½ watt
47	1214564	3.3 megohms, ½ watt, ±5%
48	7237835	220 ohms, ½ watt
49	1213488	680,000 ohms, ½ watt

Section 2
 Chevrolet 1961
 Corvette
 Model 985003
 Date 11-28-60 (Revised)
 Page 2

SERVICE PARTS LIST

Illus. No.	Service Part No.	Description
Resistors (Continued)		
50	1213283	1.5 megohm, ½ watt
51	1213283	1.5 megohm, ½ watt
53	1213282	1.0 megohm, ½ watt
55	1213845	33,000 ohms, ½ watt, ±5%
57	1214553	47,000 ohms, ½ watt
58	1213282	1 megohm, ½ watt
59	1214556	270,000 ohms, ½ watt
60	1215944	18 ohms, ½ watt
65	1214550	22,000 ohms, ½ watt
67	1214563	2.2 megohm, ½ watt
68	1214566	4.7 megohm, ½ watt
69	7271525	100 ohms, 5 watt
70	1215107	10 ohms, ½ watt
72	1214540	56 ohms, ½ watt
73	1211005	150 ohms, 1 watt
MECHANICAL PARTS		
Chassis		
	1221119	Radiator, transistor heat
Tuner		
	1221191	Governor, gear train
123	1221132	Pushbutton, front bearing plate & slides (set of 5 buttons)
	7270395	Pushbutton, individual
Installation Parts		
	3771778	Bracket, ignition coil
	7270420	Bracket, mounting
	1947452	Capacitor, ignition coil
•	*3774770	Escutcheon, control bushing
•	*7277055	Knob, control (2)
•	*3774772	Knob, dummy
•	*3774774	Knob, tone

* Part first used in 1961.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1960-1961-corvette-service-bulletin-delco-radio-service-parts-1041.html>