

# **2008 Corvette: Customer Satisfaction Program: Keyless Access System Inoperative**

**Subject:** Bulletin GMP07-181 - 07260 Keyless Access System Inoperative,  
Models: 2008 Chevrolet Corvette

**Message #:** VSU20071584

## **DESCRIPTION:**

**CUSTOMER SATISFACTION PROGRAM #07260**

**DATED: OCTOBER 1, 2007**

**NOTE: THIS PROGRAM IS IN EFFECT UNTIL OCTOBER 31, 2008.**

On certain 2008 model year Chevrolet Corvette vehicles, the keyless access system may become inoperative at times. The doors may not automatically lock or unlock, and the vehicle may not start. The DIC will also display a "NO FOBS DETECTED" message.

If this condition occurs, the driver can lock or unlock the doors by pushing the buttons on the keyless access transmitter. The vehicle can be started by placing the transmitter in the glove box transmitter pocket with the buttons facing towards the passenger's side. Then, with the vehicle in PARK (P) for an automatic transmission, press the brake pedal and the START button. If the vehicle has a manual transmission, press the clutch and the START button.

## **CORRECTION**

Dealers are to install a new module for the keyless access system.

Refer to Customer Satisfaction Program Bulletin #07260 for the service procedure and other detailed information.

## **EFFECTIVE DATE:**

Owner mailing is scheduled to begin OCTOBER 8, 2007.

**GENERAL INFORMATION:**

PART IS RESTRICTED. PLEASE CONTACT PRODUCT QUALITY CENTER AT 1-866-654-7654 TO ORDER.

The Parts list follows:

Part Number	Description	Quantity/Vehicle
25882862	RECEIVER, R/CON DR LK & THEFT DTRNT	1

**VIN RANGE IS: From 85105302 thru 85106987**

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

COPYRIGHT GENERAL MOTORS CORPORATION. ALL RIGHTS RESERVED.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2008-corvette-customer-satisfaction-program-keyless-access-system-inoperative-168.html>