

# 2005 - 2007 Corvette: Service Bulletin: Low Tire Pressure, Leaking Cast Aluminum Wheels

**Bulletin No:** 05-03-10-003B

**Date:** April, 2006

**Subject:** Low Tire Pressure, Leaking Cast Aluminum Wheels (Repair with Adhesive Sealant)

**Models:**

2007 and Prior GM Passenger Cars and Light Duty Trucks (including Saturn)  
2003-2007 HUMMER H2  
2006-2007 HUMMER H3  
2006-2007 Saab 9-7X  
with Cast Aluminum Wheels

**NOTE:** This bulletin is being revised to add the 2007 model year and include Saturn, Saab 9-7X models and Canadian dealers. Please discard Corporate Bulletin Number 05-03-10-003A (Section 03 -- Suspension).

The complete, two page PDF file of this bulletin is linked below:

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2007-corvette-service-bulletin-low-tire-pressure-leaking-cast-aluminum-wheels-196.html>