

# 1984 - 1989 Corvette: Service Bulletin: Revised Procedure - Install or Connect Intake Manifold

**Source:** Chevrolet Dealer Service Update Bulletin

**Number:** 89-138-6A

**Section:** 6A

**Date:** April, 1989

**Subject:** Revised Procedure - Install or Connect Intake Manifold

**Model Year:** 1984-1989 Y-Car

**TO: ALL CHEVROLET DEALERS**

This revises information under "Install or Connect Intake Manifold" found on page 6A1-5 of the 1984-1989 Corvette Service Manuals.

When installing intake manifold gaskets on the cylinder heads, the coolant passage restrictors (blocked openings) should be positioned at the rear of the engine with the tabs on the intake manifold gaskets being positioned at the front of the engine.

COPYRIGHT 1989  
CHEVROLET MOTOR DIVISION  
GENERAL MOTORS CORPORATION  
ALL RIGHTS RESERVED

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1984-1989-corvette-service-bulletin-revised-procedure-install-or-connect-intake-manifold-548.html>