

# 1965 Corvette: Chevrolet Engineering Service Letter: Telescoping Steering Wheel Horn button Cap Liner - (No. 42)

---

**Subject:** Telescoping Steering Wheel Horn button Cap Liner - (No. 42)

**Model and Year:** 1965 Corvette and Corvair

**Date:** 11-2-64

**Source:** Chevrolet Engineering Service Letter

A horn button cap nylon retainer has been released to improve appearance and reduce horn blowing effort. The liner also replaces the spring, and should be used to correct complaints of excessive horn button cap vibration on early production vehicles.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=909>