

1982 Corvette: Service News: Fuel injection Diagnosis Chart

Subject: Fuel injection Diagnosis Chart

Model and Year: 1982 Corvette

Source: Chevrolet Service News


Page Number: Page 5

Date: January/February 1983 - Volume 55 - Number 1

**CODE 24
1982 FUEL INJECTION
VEHICLE SPEED SENSOR (VSS)**

NOTICE: A False Code 24 and "Check Engine" light may be set if engine is run above 1200 RPM in Neutral on vehicles equipped with manual transmission. To prevent misdiagnosis, disregard Code 24 if set under these circumstances.

- Speedometer working OK.
- Lift drive wheels.
- Back probe white ECM connector Pin 2, signal CKT 437 with a voltmeter to ground.
- Ignition "ON."
- Transmission in "NEUTRAL."
- Rotate drive wheel manually while observing voltage. Be sure opposite wheel does not turn.



Clear codes and confirm "Closed Loop" operation and no "Check Engine" light.




Fig. 2 — TC 24-Vehicle Speed Sensor

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1982-corvette-service-news-fuel-injection-diagnosis-chart-937.html>