

# 1963 Corvette: Service Bulletin: Improved Vacuum Modulator

**Subject:** Improved Vacuum Modulator  
**Model and Year:** 1963 Aluminum Powerglide  
**Source:** Chevrolet Technical Service Bulletin  
**Bulletin No:** DR #568  
**Section:** VII  
**Date:** December 17, 1962

TO: ALL CHEVROLET DEALERS

An improved vacuum modulator system has been incorporated in the 1963 Aluminum Powerglide transmission effective at start of production at Cleveland and beginning with transmission code #T911 at Toledo. Modulator parts are not interchangeable between old and new design. If service is required, replace parts must be same type as original equipment.

The old and new vacuum modulator systems are illustrated on the reverse side. Parts data is also included to enable the correct parts to be obtained in the event replacement is required.

ALL 1962 AND  
EARLY 1963  
TOLEDO  
TRANSMISSIONS

3789122

ALL 1963  
CLEVELAND AND  
1963 TOLEDO DATE  
STAMPED  
T911 AND LATER

3830276

DESCRIPTION

Vacuum Modulator  
Valve

---


3830311

Vacuum Modulator  
Valve Plunger


3812741

3830229

Vacuum Modulator  
Assem.



ALL 1962 AND EARLY 1963 TOLEDO TRANSMISSIONS



ALL 1963 CLEVELAND AND 1963 TOLEDO  
DATE STAMPED T911 AND LATER

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1963-corvette-service-bulletin-improved-vacuum-modulator-957.html>